



SERVICE BULLETIN

© Carrier Corporation 2014

Number: SMB 09-0024A

Title: Enhanced Warranty Policy – 40” Tall,
Multipoise 90% Furnace Secondary
Heat Exchanger Failures

Author: Chris Kafura

Category: Policy

Dealer Bulletin Number: None

Issued: 6/8/09 SMB 07-0056

Revision: 04/01/2018

Expires: This Policy will be reviewed and updated semi-annually.

Dept: Building & Industrial
Systems

PRODUCT CATEGORY:

90% Gas Furnaces

MODELS AFFECTED:

340A, 340M, 345M, 350A, 350M, 351D, 352A, 352M, 355A, 355B, 355C,
355M

58MCA, MCB, MXA, MXB, MSA, UVB, MVP, MVB, MVC, MTA, MTB

490A, PG9M

Serial Number Range: 2993A00001 – 1808A99999

SITUATION:

In response to customer feedback, actions are being taken to simplify the administrative work associated with submitting claims for secondary or “condensing” heat exchangers or furnaces with a failed secondary heat exchanger that meet the criteria in SMB 09-0022. **Changes are indicated by bold text.**

Carrier provides an enhanced warranty on the secondary or “condensing” heat exchangers for the above listed 90% high-efficiency furnace models, within the stated serial number ranges. This bulletin provides details of the warranty coverage policies and claim process updates. This policy ONLY covers the failure and required replacement of a secondary or “condensing” heat exchanger and the following related parts: coupling box kits, cold spot baffle, and cell inlet and outlet panels.

Failure or imminent failure within 6 months is defined by the following criteria:

1. The furnace no longer functions to produce heat due to diagnosed heat exchanger restriction per inspection guidelines provided in SMB 09-0022.
2. The furnace produces heat but fails combustion analysis test due to heat exchanger restriction as diagnosed per guidelines provided in SMB 09-0022.
3. The secondary heat exchanger meets the visual inspection failure criteria per visual inspection instructions provided in SMB 09-0022.

The coverage period for this policy is twenty (20) years from original furnace installation date.

SOLUTION:

This enhanced warranty policy provides two coverage options:

Option #1: Flat Rate Allowance to cover the replacement of a failed secondary heat exchanger.

Option #2: Monetary credit allowance toward the purchase of a new piece of equipment.

Note: Option #2 is only available toward Carrier, Bryant and Payne brand equipment that has a minimum retail value of \$1250.00 (not including the cost of installation).

Field Action:

All dealers and service contractors should refer to SMB 09-0022 / DSB 09-0022 “90% Furnace Heat Exchanger Inspection Procedure” to properly troubleshoot and inspect 90% furnace heat exchangers.

This policy update is effective for secondary heat exchangers with failure dates of January 14th, 2014 or later.

Unless otherwise notified by the distributor, **dealers must return secondary heat exchangers from replaced furnaces or the entire furnace from sites that selected Policy Option #2 to the distributor for potential factory audit. It is no longer necessary to return replaced heat exchangers from sites that selected Policy Option #1.** A copy of the 90% Furnace Secondary Heat Exchanger Inspection Certificate must also be attached to or held with the secondary heat exchanger part **or furnace**. All secondary heat exchangers from replaced furnaces **or whole furnaces** replaced under this Policy must be held at the distributor for potential factory inspection for thirty (30) days from distributor claim paid date.

POLICY:

This policy ONLY covers the failure and required replacement of a secondary or “condensing” heat exchanger and the following related parts: coupling box kits, cold spot baffle, collector box, and cell inlet and outlet panels. Additionally, this bulletin takes precedent over any extended optional contract. All secondary heat exchanger claims for any 90% furnace that is covered by an extended optional contract should be claimed against this bulletin and not against the extended optional contract.

Policy Option #1: Replacement of a failed secondary heat exchanger

This option will provide a flat rate allowance to cover labor. The allowance amounts are set at the individual dealer level to allow for proper reimbursement based on registered street rates of 4 hours. All parts associated with the repair must be claimed under the bulletin. This policy option only provides a flat rate labor allowance.

Use SMB090024A in the Service Bench warranty system to file a claim for policy option #1.

The dealer shall not charge the end-user customer labor for the replacement of the secondary heat exchanger and associated ancillary parts covered under this policy option.

Policy Option #2: Monetary credit allowance toward purchase of a piece of new equipment

This option will provide a monetary credit allowance toward the purchase of a new piece of equipment. This credit must be used to purchase a new Carrier, Bryant or Payne piece of equipment having a minimum retail value of \$1250.00 (not including the cost of installation). The credit cannot be used to purchase a number of different heating or cooling products that together exceed \$1,250. The credit may not be used on multiple occasions, and may not be aggregated. If the credit exceeds the purchase price of the new piece of equipment, the consumer is not entitled to a refund of the

Excess amount, nor may they apply the excess amount to another piece of Carrier, Bryant or Payne equipment.

The credit allowance will provide a flat rate allowance based on registered street rates of 4 hours plus \$200 parts credit.

Use SMB090024B in the Service Bench warranty system to file a claim for Policy Option #2.

Note: All secondary heat exchangers from replaced furnaces **or whole furnaces** replaced under Policy **Option #2** must be held for potential factory inspection for thirty (30) days from distributor claim paid date. A copy of the 90% Furnace Secondary Heat Exchanger Inspection Certificate must be retained with the secondary heat exchanger part **or furnace**. **The certificate must be retained after the part or furnace is scrapped.**

Bulletin #	HRS	MATERIAL DOLLARS	DESCRIPTION
SMB090024A	Flat Rate	N/A	Replacement of a failed Secondary Heat Exchanger
SMB090024B	Flat Rate	\$200	Credit Allowance towards purchase of a piece of new equipment.

This Policy will be reviewed and updated semi-annually.

90% Furnace Secondary Heat Exchanger Inspection Certificate			
A copy of this certificate must be held at the distributor with the part or furnace. Following part or furnace scrapping, retain the certificate for potential factory audit.			
**SCA(s)			
**Customer Name			
**Customer Address			
**Customer Phone #			
**Model Number		**Serial Number	
Combustion Test Checklist			
**CO reading – Required if furnace is operational			ppm
Excess air level			%
Installation Checklist – check all areas examined per SMB09-0022			
Venting		Condensate Drain	Pressure Switch Hoses
Start-up		Propane Conversion	Thermostat Set Up
Safety Control Check		Accessories	Propane Conversion
Maintenance Items – check all items cleaned or examined per SMB09-0022			
Air Filter(s)		Blower Motor/Wheel	Burners/Igniter
Primary Heat Exchanger		Secondary Heat Exchanger	Electrical Connections
Other Tubing/Hoses			
After installation and maintenance items corrected - Combustion retest			
CO reading (2 nd) test			ppm
Excess air level (2 nd) test			%
Visual Inspection of Secondary Heat Exchanger			
**Observations from visual inspection of heat exchanger			
**If furnace is replaced provide replacement model and serial number			
**Model Number		**Serial Number	
**Dealer Name/ Dealer Number			
**Technician Name (Print)			
**Technician Signature			
I certify that the secondary heat exchanger in this unit failed or that failure was deemed imminent based on observations documented in this inspection certificate.			
		** Denotes Required Field	